Approved For Release 2002/07/10 : CIA-RDP78B04747A000900050013-4

31 Aug. 62

STATINTL

STATINTL

On 30 Aug [redacted] called me at home to inform me that the plotter cost would be [redacted] and that the proposal would be here shortly, and that he had the price information on the Army's on line [redacted] about that it was at the office

STATINTL
STATINTL
STATINTL

On 31 Aug I called [redacted] for the Dataphone hook up price. The telephone quotes were [redacted] for the 1st unit and [redacted] for each additional unit. Delivery would be 6 months for relay output and 10 months for transistor output. It would cost an additional [redacted] for typewriter output if required along with the Dataphone output.

STATINTL

STATINTL

[redacted]

STATINTL

Declass Review by NIMA/DOD

Approved For Release 2002/07/10 : CIA-RDP78B04747A000900050013-4

Approved For Release 2002/07/10 : CIA-RDP78B04747A000900050013-4

10 April

Memo For the Record.

STATINTL

Discussed Army [redacted] equipment

STATINTL

procurement [redacted] today and pointed

STATINTL

out that now is the times to review his [redacted]

requirements before the contract is let. He

stated that he definately wants it on line

STATINTL

and I requested that he inform [redacted] in

writing to that effect.

[redacted] STATINTL

Approved For Release 2002/07/10 : CIA-RDP78B04747A000900050013-4

Approved For Release 2002/07/10 : CIA-RDP78B04747A000900050013-4

23 Jan 62

Memo For Record:

STATINTL

STATINTL Subject: [redacted] Spare Parts [redacted] STATINTL

STATINTL

1. Reference telephone conversation [redacted] [redacted] TP&DS.

STATINTL

STATINTL 2. [redacted] said that the [redacted] home office has sent a list of spare parts [redacted] said that he STATINTL did not know when the list would arrive here as STATINTL the [redacted] people did not always move quickly.

STATINTL

3. He will notify [redacted] when the list arrives.

[redacted] STATINTL

Approved For Release 2002/07/10 : CIA-RDP78B04747A000900050013-4

Approved For Release 2002/07/10 : CIA-RDP78B04747A000900050013-4

STAT

STATINTL [redacted] — Coordinate with

[redacted] on

what maintenance arrangements we want

STAT to make for the [redacted]. Then prepare

a paper for Committee approval -

MWK

Approved For Release 2002/07/10 : CIA-RDP78B04747A000900050013-4

Approved For Release 2002/07/10 : CIA-RDP78B04747A000900050013-4

20 March

STATINTL

Telecoms [redacted]

STATINTL

STATINTL [redacted] phoned today to inform me that she had contacted [redacted] and that they couldn't have their technicians here before the 27th, and that only 2 of the 3 could come at that time. The names of the men that would first arrive were not given STATINTL [redacted] she will get the names next time she contacts them.

STATINTL

The tape panel is at [redacted] and will be brought over by [redacted]

STATINTL

Approved For Release 2002/07/10 : CIA-RDP78B04747A000900050013-4

Approved For Release 2002/07/10 : CIA-RDP78B04747A000900050013-4

March 19, 62

Telecon [redacted] STATINTL

STATINTL

STATINTL

Have requested that [redacted] technicians plan to be here on the 21st march [redacted] STATINTL called [redacted] and could not locate anyone with authority to send the men here. She is to try again tomorrow.

STATINTL

STATINTL [redacted] also received cable [redacted] advising [redacted] STATINTL control panned switch board with connecting cables was not shipped with instrument #1 shipped March 9th. It has been shipped by air under seperate cover and [redacted] will deliver as soon as it arrives [redacted] STATINTL

STATINTL

[redacted]

STATINTL

Approved For Release 2002/07/10 : CIA-RDP78B04747A000900050013-4

Approved For Release 2002/07/10 : CIA-RDP78B04747A000900050013-4

29 June 61

STATINTL [redacted] called to say the magnifications on the [redacted] STAT will be 18x, 14x 10.5x, 7.5x 5.8x*, and 4.9x.

Carriage movement will be via headcam.

Approved For Release 2002/07/10 : CIA-RDP78B04747A000900050013-4